

CORRECTION

For the article titled “Impact of endograft design and product line on the device cost of endovascular aneurysm repair”, published in J Vasc Surg 2008;47:499-503, in the last row and last column of Table III, there should be a “–” (negative sign) in front of “\$216”.